


LEAK DETECTOR INSTALLATION DIAGRAMS

Leak detector installation in single-phase or three-phase Trydan e-Chargers


To carry out the installation, the connector of the leak detector must be placed in the J1 port located on the power board. Subsequently, the cables coming out of the power board must be routed to the charging hose inside the coil, depending on the type of installation (single-phase or three-phase). See next page:



LEAK DETECTOR INSTALLATION DIAGRAMS

Single-phase installation

Run the following wires from the power board to the hose: Neutral (blue) and Phase 1 (brown) inside the coil. Always leave the earth wire (yellow and green) outside.



Three-phase installation

Run the following wires from the power board to the hose: Neutral (blue), Phase 1 (brown), Phase 2 (black) and Phase 3 (grey) inside the coil. Leaving always the earth wire (yellow and green) outside.

